

Air Duct Cleaning Report

DUCTZ cleaned the air duct and hvac system at the home of:

Recent Customer

(name removed to protect our customer) **Bel Air MD**May 8, 2014

Following are the photos taken during the cleaning process



Scott Jasion, owner

DUCTZ of the Upper Bay Region ductz-upperbay.com

410-692-9775



Supply branch before cleaning (shows significant effect of smoking in the home)




IMG_6806




After cleaning



IMG_6807



before




IMG_6812




after



IMG_6813




before



IMG_6818



after




IMG_6819



Blower motor before cleaning




Blower wheel before




after



After (type-2 cleaning)





Supply trunk before cleaning



After cleaing







before after



Summary

The Air Duct Cleaning at this home went well with no issues. We also replaced the furnace filter, and recommend continued use of a Merv8 (FPR4) or higher rated pleated filter to maintain system cleanliness and good air quality in your home.

Thank You!



Customers like you are the foundation of our business. It has been a pleasure serving you and we want you to know we appreciate your business.

We depend on your referrals! DUCTZ prides itself on doing top quality work, and we want to be sure you are completely delighted with your DUCTZ experience. If that is not the case, I would appreciate it if you would give us a chance to address your concerns by calling me directly (up till 10pm) at 410-692-9775.

- Scott Jasion



DUCTZ of the Upper Bay Region

410-692-9775

Locally owned – Nationally known

P.S. Who do you know that would love to have DUCTZ kind of professional service? **P.P.S.** Please don't keep us a secret!